



**IMPORTANT:**  
 WHEN TESTING CURTAIN FOR THE FIRST TIME, ENSURE BOTH MOTORS ARE ROTATING IN THE CORRECT DIRECTION. TEST WITH A SHORT TURN OF THE KEYSWITCH, CONTINUING TO OPERATE CURTAIN IF MOTORS ARE NOT ROTATING IN THE CORRECT DIRECTION WILL CAUSE DAMAGE TO THE CURTAIN.

MOTOR TYPE *	AMPS	RPM	TORQUE
85mm DRIVE TUBE	3.8	14	100Nm
120mm DRIVE TUBE	5.6	10	200Nm

\* REFER TO SHOP DRAWING

3 POSITION MOMENTARY KEYSWITCH PROVIDED BY FORUM ATHLETIC REQUIRES DEEP SINGLE GANG BOX BY OTHERS LOCATE TO ALLOW OPERATOR CLEAR VIEW OF DIVIDER CURTAIN

NOTES:

**FORUM**  
 Athletic Products Inc  
 9 Browning Court Unit 1, Bolton, ON L7E 1G8  
 P. (905) 405-1222 F. (905) 405-8532

PRODUCT:  
**DUAL MOTOR F3500/F3505 DIVIDER CURTAIN WIRING DIAGRAM**

DRAWN BY: S. STRAZZABOSCO	SCALE: NTS	SHEET No: 1 OF 1
DATE: AUGUST 28, 2018	JOB No:	